
Meridian 1

Message Center

Description and operation

Document Number: 553-2691-100

Document Release: Standard 8.00

Date: August 1996

© 1980, 1996

All rights reserved

Printed in the United States of America

Information is subject to change without notice. Northern Telecom reserves the right to make changes in design or components as progress in engineering and manufacturing may warrant. This equipment has been tested and found to comply with the limits for a Class A digital device pursuant to Part 15 of the FCC rules, and the radio interference regulations of Industry Canada. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses and can radiate radio frequency energy, and if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference in which case the user will be required to correct the interference at their own expense.

SL-1 and Meridian 1 are trademarks of Northern Telecom.

Revision history

August 1996

Standard, Release 8.00. Reissued for X11 Release 22.0x.

December 1994

Standard, Release 7.00. Reissued to include editorial changes and indexing. Due to the extent of the changes, revision bars are not used.

August 1993

Standard, release 6.00. Reissued to include changes for X11 Release 19.

December 1992

Standard, release 5.00. Reissued to include changes for X11 Release 18.

December 1991

Standard, release 4.00. This document is reissued to include technical content updates. Due to the extent of changes, revision bars are not used.

December 1990

Standard, release 3.00. Reissued to include updates for X11 Release 16.

June 1990

Standard, release 2.00. Reissued for additional X11 Release 15 changes.

December 1989

Standard, release 1.00. Reissued for compliance with Northern Telecom Standard 164.0 and to include updates for X11 Release 15.

Contents

Description	1
Reference documentation	1
Incoming calls to the Message Center	2
Direct message calls	2
Indirect message calls	2
Operation	2
Automatic Call Distribution (ACD) Message Center	3
Telephone Message Center	4
Attendant Message Center	6
Message retrieval calls	8
Placing a message retrieval call	9
Answering a message retrieval call	10
Direct Message Waiting lamp control	11
Query and/or activate	11
Query and/or deactivate	12
Network Message Service (NMS)	12
Feature requirements	13
Implementation	13
Message Waiting Indication (MWI) Interworking	14
Feature requirements	15
Equipment requirements	17
User telephones	17
SL-1 telephones with Message Waiting key/lamp pair	17
500 telephones	17
2500 telephones	17

Standard 500/2500 and SL-1 telephones	18
Message Waiting lamp requirements	18
Message Center telephones	19
SL-1 telephones	19
Attendant Consoles	19
Network Message Services	20
MWI Interworking	21
System requirements	23
QSY22 Power Supply	23
Description	24
Mounting	24
QSY19 Power Supply	27
QBL16 Power Distribution Unit	27
Mounting	27
PE cabinets and shelves	32
Line circuit cards	32
Maintenance	33
Power supply installation	35
QSY22	35
QBL16	37
Feature interaction	39
Message Center packaging	43

List of figures

Figure 1	
QSY22 Power Supply connections	25
Figure 2	
QSY22 Power Supply circuit diagram	26
Figure 3	
QSY19 Power Supply connections	
(This unit is no longer available)	28
Figure 4	
QSY19 Power Supply circuit diagram	29
Figure 5	
QBL16 Power Distribution Unit connections	30
Figure 6	
QBL16 Power Distribution Unit circuit diagram	31